


1ZS93100E

Panama súprava pre minibus MB Sprinter N63



Poz.1	Poz.2	Názov	Interný kód	ks
1		Súprava sania vzduchu	U003AA141	1
	2	Súprava skrutiek (6ks M4x15mm; 12ks 4,2x25mm)	0231817	1
3		Hadica A/C Manuli Refrimaster G10 1/2"	90010G2GRFR	8m
4		Hadica A/C Manuli Refrimaster G12 5/8"	90012G2GRFR	8m
5		Kabeláž napájacia 13m	0282542	1
6		Balenie s koncovkami A/C	0231950	1
	7	Koncovka hadice A/C Frigoclic 11/16"; hadica G12 5/8"; závit	80112FS006	1
	8	Koncovka hadice A/C Frigoclic 5/8"; hadica G10 1/2"; závit vnút.	80110FS049	1
	9	Koncovka hadice A/C Frigoclic 1/2"; hadica G10 1/2"; závit vnút.	80110FS038	1
	10	Spojka hadice A/C Frigoclic 5/8"; hadica G10 1/2"; hadica G10	80110FS048	1
	11	Koncovka hadice A/C Frigoclic 5/8"; hadica G12 5/8"; závit vnút.	80112FS007	1
	12	Spojka hadice A/C Frigoclic 11/16"; hadica G12 5/8"; hadica G12	80112FS020	1
	13	Spona G10 1/2" Frigoclic na hadicu Refrimaster DN12,7	0361780	6
	14	Spona G12 5/8" Frigoclic na hadicu Refrimaster DN16	0361781	6
	15	Štítok obsahu chladiva R134a	ETHDV00080	1
	16	Páska izolačná na trubky 0,5m	070001	1

